





R	8
	
1x	1x

4









5











3.

R

METAL ROŠŤ / MANŽELSKÁ POSTEĽ
Montážny návod

1	2	3	4	5	6
					
1x	2x	2x	lamely - 34x	17x	34x

7	8	9	10	11	12
					
4x	1 x	M6x50 - 2 x	ST 3,9x19 8 x	M8x40 - 4 x	1 x



4.