




R	8	M	N
1x	1x	5mm - 1x	4x




4

5



L1	L2	M	N
1x	1x	2x	4x



3.


R

METAL ROŠT / MANŽELSKÁ POSTEĽ

Montážny návod

1	2	3	4	5	6
1x	2x	2x	lamely - 34x	17x	34x

7	8	9	10	11	12
4x	1x	M6x50 - 2x	ST 3,9x19 8x	M8x40 - 4x	1x



4.